

# Certificate

This is to certify that **Vinidex Pty Ltd**

ABN 42 000 664 942

Head Office Address 224 Musgrave Road,  
Coopers Plains,  
Queensland, 4108,  
Australia

Holds Certificate Number **BMP 543082**

Is authorised to use the BSI registered Benchmark Product Certification Trademark, on products identified in the Product Certification Schedule that is attached to this Product Certification Certificate. Such products have been Type Tested and are manufactured under the Product Certification Requirements monitored by BSI to ensure that the manufacturing process has the capability to consistently produce products in compliance with and are Certified to:

AS/NZS 2280:2014 Ductile Iron Pipes and Fittings

For and on behalf of BSI

Marc Barnes, Managing Director, BSI Group ANZ Pty Ltd

Originally registered  
15/10/2006

Latest issue  
02/02/2016

Expiry date  
27/01/2021



...making excellence a habit.

# Schedule

This schedule supports the WaterMark Certificate of Conformity for Vinidex Pty Ltd

ABN 42 000 664 942

Head Office Address 224 Musgrave Road,  
Coopers Plains,  
Queensland, 4108,  
Australia

Holds Certificate Number BMP 543082

Standard AS/NZS 2280:2014 Ductile Iron Pipes and Fittings

Issue date 02/02/2016

Model ID	Product Description		BSI Review Date
77584	Superlink II	Bend 100 11.25 SOC-SOC	21/10/2010
77585	Superlink II	Bend 100 22.5 SOC-SOC	21/10/2010
77586	Superlink II	Bend 100 45 SOC-SOC	21/10/2010
77587	Superlink II	Bend 100 90 SOC-SOC	21/10/2010
77588	Superlink II	Bend 150 11.25 SOC-SOC	21/10/2010
77589	Superlink II	Bend 150 22.5 SOC-SOC	21/10/2010
77590	Superlink II	Bend 150 45 SOC-SOC	21/10/2010
77591	Superlink II	Bend 150 90 SOC-SOC	21/10/2010
77618	Superlink II	Bend 200 11.25 SOC-SOC	21/10/2010
77621	Superlink II	Bend 200 22.5 SOC-SOC	21/10/2010
77623	Superlink II	Bend 200 45 SOC-SOC	21/10/2010
77631	Superlink II	Bend 200 90 SOC-SOC	21/10/2010
77855	Superlink II	Bend 225 11.25 SOC-SOC	21/10/2010

BMP 543082

02/02/2016 Page 2 of 18



...making excellence a habit.

# Schedule

Model ID	Product Description	BSI Review Date
77865	Superlink II Bend 225 22.5 SOC-SOC	21/10/2010
77885	Superlink II Bend 225 45 SOC-SOC	21/10/2010
77905	Superlink II Bend 225 90 SOC-SOC	21/10/2010
77915	Superlink II Bend 250 11.25 SOC-SOC	21/10/2010
77925	Superlink II Bend 250 22.5 SOC-SOC	21/10/2010
77945	Superlink II Bend 250 45 SOC-SOC	21/10/2010
77965	Superlink II Bend 250 90 SOC-SOC	21/10/2010
77617	Superlink Bend 100 11.25 SOC-SOC	21/10/2010
77626	Superlink Bend 100 22.5 SOC-SOC	21/10/2010
77646	Superlink Bend 100 45 SOC-SOC	21/10/2010
77667	Superlink Bend 100 90 SOC-SOC	21/10/2010
77676	Superlink Bend 150 11.25 SOC-SOC	21/10/2010
77686	Superlink Bend 150 22.5 SOC-SOC	21/10/2010
77706	Superlink Bend 150 45 SOC-SOC	21/10/2010
77726	Superlink Bend 150 90 SOC-SOC	21/10/2010
77796	Superlink Bend 200 11.25 SOC-SOC	21/10/2010
77806	Superlink Bend 200 22.5 SOC-SOC	21/10/2010
77826	Superlink Bend 200 45 SOC-SOC	21/10/2010
77846	Superlink Bend 200 90 SOC-SOC	21/10/2010
77851	Superlink Bend 225 11.25 SOC-SOC	21/10/2010
77861	Superlink Bend 225 22.5 SOC-SOC	21/10/2010
77881	Superlink Bend 225 45 SOC-SOC	21/10/2010
77901	Superlink Bend 225 90 SOC-SOC	21/10/2010
77916	Superlink Bend 250 11.25 SOC-SOC	21/10/2010
77926	Superlink Bend 250 22.5 SOC-SOC	21/10/2010
77946	Superlink Bend 250 45 SOC-SOC	21/10/2010
77966	Superlink Bend 250 90 SOC-SOC	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
77976	Superlink	Bend 300 11.25 SOC-SOC	21/10/2010
77986	Superlink	Bend 300 22.5 SOC-SOC	21/10/2010
78006	Superlink	Bend 300 45 SOC-SOC	21/10/2010
78026	Superlink	Bend 300 90 SOC-SOC	21/10/2010
78035	Superlink	Bend 375 11.25 SOC-SOC	21/10/2010
78606	Superlink	Bend 375 22.5 SOC-SOC	21/10/2010
78070	Superlink	Bend 375 45 SOC-SOC	21/10/2010
78607	Superlink	Bend 375 90 SOC-SOC	21/10/2010
77636	Superlink II	Connector 100 FL-SP	21/10/2010
77637	Superlink II	Connector 150 FL-SP	21/10/2010
77638	Superlink II	Connector 200 FL-SP	21/10/2010
77639	Superlink II	Connector 225 FL-SP	21/10/2010
77640	Superlink II	Connector 250 FL-SP	21/10/2010
80109	Superlink	Connector 100 FL-SP	21/10/2010
80119	Superlink	Connector 150 FL-SP	21/10/2010
80135	Superlink	Connector 200 FL-SP	21/10/2010
80149	Superlink	Connector 225 FL-SP	21/10/2010
80159	Superlink	Connector 250 FL-SP	21/10/2010
80169	Superlink	Connector 300 FL-SP	21/10/2010
78838	Superlink	Connector 375 FL-SP	21/10/2010
77641	Superlink II	Connector 100 SOC-SOC	21/10/2010
77643	Superlink II	Connector 150 SOC-SOC	21/10/2010
77648	Superlink II	Connector 200 SOC-SOC	21/10/2010
80255	Superlink II	Connector 225 SOC-SOC	21/10/2010
80265	Superlink II	Connector 250 SOC-SOC	21/10/2010
80216	Superlink	Connector 100 SOC-SOC	21/10/2010
80226	Superlink	Connector 150 SOC-SOC	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
80246	Superlink	Connector 200 SOC-SOC	21/10/2010
80256	Superlink	Connector 225 SOC-SOC	21/10/2010
80266	Superlink	Connector 250 SOC-SOC	21/10/2010
80276	Superlink	Connector 300 SOC-SOC	21/10/2010
78833	Superlink	Connector 375 SOC-SOC	21/10/2010
77649	Superlink II	Connector - Ready Tap 100x4x20 SOC-SOC	21/10/2010
80217	Superlink II	Connector - Ready Tap 100x1x50 SOC-SOC	21/10/2010
77650	Superlink II	Connector - Ready Tap 150x4x20 SOC-SOC	21/10/2010
80227	Superlink II	Connector - Ready Tap 150x1x50 SOC-SOC	21/10/2010
81240	Superlink	Connector - Ready Tap 100x4x20 SOC-SOC	21/10/2010
81243	Superlink	Connector - Ready Tap 100x4x25 SOC-SOC	21/10/2010
78840	Superlink	Connector - Ready Tap 100x1x50 SOC-SOC	21/10/2010
81242	Superlink	Connector - Ready Tap 150x4x20 SOC-SOC	21/10/2010
81244	Superlink	Connector - Ready Tap 150x4x25 SOC-SOC	21/10/2010
78841	Superlink	Connector - Ready Tap 150x1x50 SOC-SOC	21/10/2010
80548	Superlink	Cap 100	21/10/2010
80553	Superlink	Cap 150	21/10/2010
80560	Superlink	Cap 200	21/10/2010
80567	Superlink	Cap 225	21/10/2010
80574	Superlink	Cap 250	21/10/2010
80581	Superlink	Cap 300	21/10/2010
80586	Superlink	Cap 375	21/10/2010
80811	Superlink	Hydrant Riser 80x100 FL-FL	21/10/2010
80821	Superlink	Hydrant Riser 80x150 FL-FL	21/10/2010
80831	Superlink	Hydrant Riser 80x225 FL-FL	21/10/2010
80841	Superlink	Hydrant Riser 80x300 FL-FL	21/10/2010
80851	Superlink	Hydrant Riser 80x375 FL-FL	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
80861	Superlink	Hydrant Riser 80x450 FL-FL	21/10/2010
80867	Superlink	Hydrant Riser 80x600 FL-FL	21/10/2010
80894	Superlink	Hydrant Riser 100x100 FL-FL	21/10/2010
80895	Superlink	Hydrant Riser 100x150 FL-FL	21/10/2010
80901	Superlink	Hydrant Riser 100x225 FL-FL	21/10/2010
80903	Superlink	Hydrant Riser 100x300 FL-FL	21/10/2010
80905	Superlink	Hydrant Riser 100x375 FL-FL	21/10/2010
80907	Superlink	Hydrant Riser 100x450 FL-FL	21/10/2010
80909	Superlink	Hydrant Riser 100x600 FL-FL	21/10/2010
77651	Superlink II	Taper 150-100 Conc SOC-SOC	21/10/2010
77652	Superlink II	Taper 200-100 Conc SOC-SOC	21/10/2010
77653	Superlink II	Taper 200-150 Conc SOC-SOC	21/10/2010
79775	Superlink II	Taper 225-100 Conc SOC-SOC	21/10/2010
79785	Superlink II	Taper 225-150 Conc SOC-SOC	21/10/2010
79795	Superlink II	Taper 225-200 Conc SOC-SOC	21/10/2010
79805	Superlink II	Taper 250-100 Conc SOC-SOC	21/10/2010
79815	Superlink II	Taper 250-150 Conc SOC-SOC	21/10/2010
79825	Superlink II	Taper 250-200 Conc SOC-SOC	21/10/2010
79835	Superlink II	Taper 250-225 Conc SOC-SOC	21/10/2010
79747	Superlink	Taper 150-100 Conc SOC-SOC	21/10/2010
79756	Superlink	Taper 200-100 Conc SOC-SOC	21/10/2010
79766	Superlink	Taper 200-150 Conc SOC-SOC	21/10/2010
79776	Superlink	Taper 225-100 Conc SOC-SOC	21/10/2010
79786	Superlink	Taper 225-150 Conc SOC-SOC	21/10/2010
79796	Superlink	Taper 225-200 Conc SOC-SOC	21/10/2010
79806	Superlink	Taper 250-100 Conc SOC-SOC	21/10/2010
79816	Superlink	Taper 250-150 Conc SOC-SOC	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
79826	Superlink	Taper 250-200 Conc SOC-SOC	21/10/2010
79836	Superlink	Taper 250-225 Conc SOC-SOC	21/10/2010
79844	Superlink	Taper 300-100 Conc SOC-SOC	21/10/2010
79849	Superlink	Taper 300-150 Conc SOC-SOC	21/10/2010
79856	Superlink	Taper 300-200 Conc SOC-SOC	21/10/2010
79866	Superlink	Taper 300-225 Conc SOC-SOC	21/10/2010
79876	Superlink	Taper 300-250 Conc SOC-SOC	21/10/2010
78737	Superlink	Taper 375-100 Conc SOC-SOC	21/10/2010
78738	Superlink	Taper 375-200 Conc SOC-SOC	21/10/2010
78740	Superlink	Taper 375-225 Conc SOC-SOC	21/10/2010
79916	Superlink	Taper 375-250 Conc SOC-SOC	21/10/2010
81649	Superlink	Taper 375-300 Conc SOC-SOC	21/10/2010
77654	Superlink II	Taper 100-80 Conc SOC-FL	21/10/2010
77655	Superlink II	Taper 150-80 Conc SOC-FL	21/10/2010
79743	Superlink II	Taper 150-100 Conc SOC-FL	21/10/2010
77656	Superlink II	Taper 200-100 Conc SOC-FL	21/10/2010
77657	Superlink II	Taper 200-150 Conc SOC-FL	21/10/2010
78798	Superlink II	Taper 225-100 Conc SOC-FL	21/10/2010
78800	Superlink II	Taper 225-150 Conc SOC-FL	21/10/2010
78802	Superlink II	Taper 225-200 Conc SOC-FL	21/10/2010
78804	Superlink II	Taper 250-100 Conc SOC-FL	21/10/2010
78806	Superlink II	Taper 250-150 Conc SOC-FL	21/10/2010
78808	Superlink II	Taper 250-200 Conc SOC-FL	21/10/2010
78810	Superlink II	Taper 250-225 Conc SOC-FL	21/10/2010
78797	Superlink	Taper 150-100 Conc SOC-FL	21/10/2010
78799	Superlink	Taper 225-100 Conc SOC-FL	21/10/2010
78801	Superlink	Taper 225-150 Conc SOC-FL	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
78803	Superlink	Taper 225-200 Conc SOC-FL	21/10/2010
78805	Superlink	Taper 250-100 Conc SOC-FL	21/10/2010
78807	Superlink	Taper 250-150 Conc SOC-FL	21/10/2010
78809	Superlink	Taper 250-200 Conc SOC-FL	21/10/2010
78811	Superlink	Taper 250-225 Conc SOC-FL	21/10/2010
78813	Superlink	Taper 300-100 Conc SOC-FL	21/10/2010
78815	Superlink	Taper 300-150 Conc SOC-FL	21/10/2010
78817	Superlink	Taper 300-200 Conc SOC-FL	21/10/2010
78819	Superlink	Taper 300-225 Conc SOC-FL	21/10/2010
78821	Superlink	Taper 300-250 Conc SOC-FL	21/10/2010
78823	Superlink	Taper 375-100 Conc SOC-FL	21/10/2010
78825	Superlink	Taper 375-200 Conc SOC-FL	21/10/2010
78827	Superlink	Taper 375-225 Conc SOC-FL	21/10/2010
78829	Superlink	Taper 375-250 Conc SOC-FL	21/10/2010
79930	Superlink	Taper 375-300 Conc SOC-FL	21/10/2010
77671	Superlink II	Tee-Air Valve & Hydrant 100-80 SOC-SP-FL	21/10/2010
77673	Superlink II	Tee-Air Valve & Hydrant 100-100 SOC-SP-FL	21/10/2010
77674	Superlink II	Tee-Air Valve & Hydrant 150-80 SOC-SP-FL	21/10/2010
77677	Superlink II	Tee-Air Valve & Hydrant 150-100 SOC-SP-FL	21/10/2010
77678	Superlink II	Tee-Air Valve & Hydrant 200-80 SOC-SP-FL	21/10/2010
77679	Superlink II	Tee-Air Valve & Hydrant 200-100 SOC-SP-FL	21/10/2010
77681	Superlink II	Tee-Air Valve & Hydrant 225-80 SOC-SP-FL	21/10/2010
77683	Superlink II	Tee-Air Valve & Hydrant 225-100 SOC-SP-FL	21/10/2010
77684	Superlink II	Tee-Air Valve & Hydrant 250-80 SOC-SP-FL	21/10/2010
77688	Superlink II	Tee-Air Valve & Hydrant 250-100 SOC-SP-FL	21/10/2010
77689	Superlink	Tee-Air Valve & Hydrant 300-80 SOC-SP-FL	21/10/2010
77690	Superlink	Tee-Air Valve & Hydrant 300-100 SOC-SP-FL	21/10/2010



# Schedule

Model ID	Product Description		BSI Review Date
-	Superlink	Tee-Air Valve & Hydrant 375-80 SOC-SP-FL	21/10/2010
-	Superlink	Tee-Air Valve & Hydrant 375-100 SOC-SP-FL	21/10/2010
77691	Superlink	Tees-Scour 150-80 SOC-SOC-FL	21/10/2010
77692	Superlink	Tees-Scour 200-80 SOC-SOC-FL	21/10/2010
79664	Superlink	Tees-Scour 225-100 SOC-SOC-FL	21/10/2010
79674	Superlink	Tees-Scour 250-100 SOC-SOC-FL	21/10/2010
-	Superlink	Tees-Scour 300-100 SOC-SOC-FL	21/10/2010
-	Superlink	Tees-Scour 300-150 SOC-SOC-FL	21/10/2010
-	Superlink	Tees-Scour 375-150 SOC-SOC-FL	21/10/2010
77597	Superlink II	Tee 100-100 SOC-SOC-SOC	21/10/2010
77598	Superlink II	Tee 150-100 SOC-SOC-SOC	21/10/2010
77599	Superlink II	Tee 150-150 SOC-SOC-SOC	21/10/2010
77693	Superlink II	Tee 200-100 SOC-SOC-SOC	21/10/2010
77694	Superlink II	Tee 200-150 SOC-SOC-SO	21/10/2010
77695	Superlink II	Tee 200-200 SOC-SOC-SOC	21/10/2010
98395	Superlink II	Tee 225-100 SOC-SOC-SOC	21/10/2010
78405	Superlink II	Tee 225-150 SOC-SOC-SOC	21/10/2010
78415	Superlink II	Tee 225-200 SOC-SOC-SOC	21/10/2010
78425	Superlink II	Tee 225-225 SOC-SOC-SOC	21/10/2010
78435	Superlink II	Tee 250-100 SOC-SOC-SOC	21/10/2010
78445	Superlink II	Tee 250-150 SOC-SOC-SOC	21/10/2010
78455	Superlink II	Tee 250-200 SOC-SOC-SOC	21/10/2010
78465	Superlink II	Tee 250-225 SOC-SOC-SOC	21/10/2010
78475	Superlink II	Tee 250-250 SOC-SOC-SOC	21/10/2010
78307	Superlink	Tee 100-100 SOC-SOC-SOC	21/10/2010
78316	Superlink	Tee 150-100 SOC-SOC-SOC	21/10/2010
78326	Superlink	Tee 150-150 SOC-SOC-SOC	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
78366	Superlink	Tee 200-100 SOC-SOC-SOC	21/10/2010
78376	Superlink	Tee 200-150 SOC-SOC-SOC	21/10/2010
78376	Superlink	Tee 200-200 SOC-SOC-SOC	21/10/2010
78397	Superlink	Tee 225-100 SOC-SOC-SOC	21/10/2010
78410	Superlink	Tee 225-150 SOC-SOC-SOC	21/10/2010
78416	Superlink	Tee 225-200 SOC-SOC-SOC	21/10/2010
78426	Superlink	Tee 225-225 SOC-SOC-SOC	21/10/2010
78436	Superlink	Tee 250-100 SOC-SOC-SOC	21/10/2010
78446	Superlink	Tee 250-150 SOC-SOC-SOC	21/10/2010
78456	Superlink	Tee 250-200 SOC-SOC-SOC	21/10/2010
78461	Superlink	Tee 250-225 SOC-SOC-SOC	21/10/2010
78476	Superlink	Tee 250-250 SOC-SOC-SOC	21/10/2010
78486	Superlink	Tee 300-100 SOC-SOC-SOC	21/10/2010
78494	Superlink	Tee 300-150 SOC-SOC-SOC	21/10/2010
78506	Superlink	Tee 300-200 SOC-SOC-SOC	21/10/2010
78509	Superlink	Tee 300-225 SOC-SOC-SOC	21/10/2010
78526	Superlink	Tee 300-250 SOC-SOC-SOC	21/10/2010
78536	Superlink	Tee 300-300 SOC-SOC-SOC	21/10/2010
-	Superlink	Tee 375-100 SOC-SOC-SOC	21/10/2010
-	Superlink	Tee 375-150 SOC-SOC-SOC	21/10/2010
78632	Superlink	Tee 375-200 SOC-SOC-SOC	21/10/2010
78634	Superlink	Tee 375-225 SOC-SOC-SOC	21/10/2010
78636	Superlink	Tee 375-250 SOC-SOC-SOC	21/10/2010
78637	Superlink	Tee 375-300 SOC-SOC-SOC	21/10/2010
78638	Superlink	Tee 375-375 SOC-SOC-SOC	21/10/2010
79307	Superlink II	Tee 100-80 SOC-SOC-FL	21/10/2010
78915	Superlink II	Tee 100-100 SOC-SOC-FL	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
79317	Superlink II	Tee 150-80 SOC-SOC-FL	21/10/2010
78935	Superlink II	Tee 150-100 SOC-SOC-FL	21/10/2010
78945	Superlink II	Tee 150-150 SOC-SOC-FL	21/10/2010
79327	Superlink II	Tee 200-80 SOC-SOC-FL	21/10/2010
78995	Superlink II	Tee 200-100 SOC-SOC-FL	21/10/2010
79017	Superlink II	Tee 200-150 SOC-SOC-FL	21/10/2010
79002	Superlink II	Tee 200-200 SOC-SOC-FL	21/10/2010
79337	Superlink II	Tee 225-80 SOC-SOC-FL	21/10/2010
79036	Superlink II	Tee 225-100 SOC-SOC-FL	21/10/2010
79046	Superlink II	Tee 225-150 SOC-SOC-FL	21/10/2010
79056	Superlink II	Tee 225-200 SOC-SOC-FL	21/10/2010
79066	Superlink II	Tee 225-225 SOC-SOC-FL	21/10/2010
79347	Superlink II	Tee 250-80 SOC-SOC-FL	21/10/2010
79086	Superlink II	Tee 250-100 SOC-SOC-FL	21/10/2010
79096	Superlink II	Tee 250-150 SOC-SOC-FL	21/10/2010
79106	Superlink II	Tee 250-200 SOC-SOC-FL	21/10/2010
79116	Superlink II	Tee 250-225 SOC-SOC-FL	21/10/2010
79126	Superlink II	Tee 250-250 SOC-SOC-FL	21/10/2010
77592	Superlink	Tee 100-80 SOC-SOC-FL	21/10/2010
77593	Superlink	Tee 100-100 SOC-SOC-FL	21/10/2010
77594	Superlink	Tee 150-80 SOC-SOC-FL	21/10/2010
77595	Superlink	Tee 150-100 SOC-SOC-FL	21/10/2010
77596	Superlink	Tee 150-150 SOC-SOC-FL	21/10/2010
77696	Superlink	Tee 200-80 SOC-SOC-FL	21/10/2010
77697	Superlink	Tee 200-100 SOC-SOC-FL	21/10/2010
77698	Superlink	Tee 200-150 SOC-SOC-FL	21/10/2010
77699	Superlink	Tee 200-200 SOC-SOC-FL	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
79335	Superlink	Tee 225-80 SOC-SOC-FL	21/10/2010
79030	Superlink	Tee 225-100 SOC-SOC-FL	21/10/2010
79045	Superlink	Tee 225-150 SOC-SOC-FL	21/10/2010
79055	Superlink	Tee 225-200 SOC-SOC-FL	21/10/2010
79065	Superlink	Tee 225-225 SOC-SOC-FL	21/10/2010
79345	Superlink	Tee 250-80 SOC-SOC-FL	21/10/2010
79085	Superlink	Tee 250-100 SOC-SOC-FL	21/10/2010
79095	Superlink	Tee 250-150 SOC-SOC-FL	21/10/2010
79105	Superlink	Tee 250-200 SOC-SOC-FL	21/10/2010
79115	Superlink	Tee 250-225 SOC-SOC-FL	21/10/2010
79125	Superlink	Tee 250-250 SOC-SOC-FL	21/10/2010
79357	Superlink	Tee 300-80 SOC-SOC-FL	21/10/2010
79146	Superlink	Tee 300-100 SOC-SOC-FL	21/10/2010
79155	Superlink	Tee 300-150 SOC-SOC-FL	21/10/2010
79166	Superlink	Tee 300-200 SOC-SOC-FL	21/10/2010
79176	Superlink	Tee 300-225 SOC-SOC-FL	21/10/2010
79186	Superlink	Tee 300-250 SOC-SOC-FL	21/10/2010
79196	Superlink	Tee 300-300 SOC-SOC-FL	21/10/2010
78639	Superlink	Tee 375-100 SOC-SOC-FL	21/10/2010
78641	Superlink	Tee 375-150 SOC-SOC-FL	21/10/2010
78643	Superlink	Tee 375-200 SOC-SOC-FL	21/10/2010
78645	Superlink	Tee 375-225 SOC-SOC-FL	21/10/2010
78646	Superlink	Tee 375-250 SOC-SOC-FL	21/10/2010
78648	Superlink	Tee 375-300 SOC-SOC-FL	21/10/2010
78649	Superlink	Tee 375-375 SOC-SOC-FL	21/10/2010
	Superlink	Tee 100-80 SP-SP-FL	21/10/2010
78911	Superlink	Tee 100-100 SP-SP-FL	21/10/2010

BMP 543082

02/02/2016 Page 12 of 18



...making excellence a habit.

# Schedule

Model ID	Product Description		BSI Review Date
	Superlink	Tee 150-80 SP-SP-FL	21/10/2010
78939	Superlink	Tee 150-100 SP-SP-FL	21/10/2010
78948	Superlink	Tee 150-150 SP-SP-FL	21/10/2010
	Superlink	Tee 200-80 SP-SP-FL	21/10/2010
78998	Superlink	Tee 200-100 SP-SP-FL	21/10/2010
79000	Superlink	Tee 200-150 SP-SP-FL	21/10/2010
79018	Superlink	Tee 200-200 SP-SP-FL	21/10/2010
	Superlink	Tee 225-80 SP-SP-FL	21/10/2010
78653	Superlink	Tee 225-100 SP-SP-FL	21/10/2010
78655	Superlink	Tee 225-150 SP-SP-FL	21/10/2010
78657	Superlink	Tee 225-200 SP-SP-FL	21/10/2010
78659	Superlink	Tee 225-225 SP-SP-FL	21/10/2010
	Superlink	Tee 250-80 SP-SP-FL	21/10/2010
78660	Superlink	Tee 250-100 SP-SP-FL	21/10/2010
78661	Superlink	Tee 250-150 SP-SP-FL	21/10/2010
78662	Superlink	Tee 250-200 SP-SP-FL	21/10/2010
78664	Superlink	Tee 250-225 SP-SP-FL	21/10/2010
78665	Superlink	Tee 250-250 SP-SP-FL	21/10/2010
	Superlink	Tee 300-80 SP-SP-FL	21/10/2010
78666	Superlink	Tee 300-100 SP-SP-FL	21/10/2010
78668	Superlink	Tee 300-150 SP-SP-FL	21/10/2010
78670	Superlink	Tee 300-200 SP-SP-FL	21/10/2010
78672	Superlink	Tee 300-225 SP-SP-FL	21/10/2010
78674	Superlink	Tee 300-250 SP-SP-FL	21/10/2010
78676	Superlink	Tee 300-300 SP-SP-FL	21/10/2010
	Superlink	Tee 375-80 SP-SP-FL	21/10/2010
78678	Superlink	Tee 375-100 SP-SP-FL	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
78680	Superlink	Tee 375-150 SP-SP-FL	21/10/2010
78682	Superlink	Tee 375-200 SP-SP-FL	21/10/2010
78684	Superlink	Tee 375-225 SP-SP-FL	21/10/2010
78686	Superlink	Tee 375-250 SP-SP-FL	21/10/2010
78688	Superlink	Tee 375-300 SP-SP-FL	21/10/2010
78690	Superlink	Tee 375-375 SP-SP-FL	21/10/2010
77609	Superlink	Bend 100 11.25 FL-FL	21/10/2010
77624	Superlink	Bend 100 22.5 FL-FL	21/10/2010
77644	Superlink	Bend 100 45 FL-FL	21/10/2010
77663	Superlink	Bend 100 90 FL-FL	21/10/2010
77672	Superlink	Bend 150 11.25 FL-FL	21/10/2010
77682	Superlink	Bend 150 22.5 FL-FL	21/10/2010
77708	Superlink	Bend 150 45 FL-FL	21/10/2010
77730	Superlink	Bend 150 90 FL-FL	21/10/2010
77797	Superlink	Bend 200 11.25 FL-FL	21/10/2010
77807	Superlink	Bend 200 22.5 FL-FL	21/10/2010
77828	Superlink	Bend 200 45 FL-FL	21/10/2010
77849	Superlink	Bend 200 90 FL-FL	21/10/2010
81657	Superlink	Bend 225 11.25 FL-FL	21/10/2010
77863	Superlink	Bend 225 22.5 FL-FL	21/10/2010
78610	Superlink	Bend 225 45 FL-FL	21/10/2010
78611	Superlink	Bend 225 90 FL-FL	21/10/2010
77917	Superlink	Bend 250 11.25 FL-FL	21/10/2010
77927	Superlink	Bend 250 22.5 FL-FL	21/10/2010
78613	Superlink	Bend 250 45 FL-FL	21/10/2010
78615	Superlink	Bend 250 90 FL-FL	21/10/2010
78617	Superlink	Bend 300 11.25 FL-FL	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
78618	Superlink	Bend 300 22.5 FL-FL	21/10/2010
78619	Superlink	Bend 300 45 FL-FL	21/10/2010
78621	Superlink	Bend 300 90 FL-FL	21/10/2010
78623	Superlink	Bend 375 11.25 FL-FL	21/10/2010
78625	Superlink	Bend 375 22.5 FL-FL	21/10/2010
78627	Superlink	Bend 375 45 FL-FL	21/10/2010
78628	Superlink	Bend 375 90 FL-FL	21/10/2010
78745	Superlink	Taper 100-80 ECCEN FL-FL	21/10/2010
78746	Superlink	Taper 150-80 ECCEN FL-FL	21/10/2010
78747	Superlink	Taper 150-100 ECCEN FL-FL	21/10/2010
78748	Superlink	Taper 200-100 ECCEN FL-FL	21/10/2010
78749	Superlink	Taper 200-150 ECCEN FL-FL	21/10/2010
79736	Superlink	Taper 100-80 CONC FL-FL	21/10/2010
	Superlink	Taper 150-80 CONC FL-FL	21/10/2010
78750	Superlink	Taper 150-100 CONC FL-FL	21/10/2010
768751	Superlink	Taper 200-100 CONC FL-FL	21/10/2010
78752	Superlink	Taper 200-150 CONC FL-FL	21/10/2010
78753	Superlink	Taper 225-100 CONC FL-FL	21/10/2010
78755	Superlink	Taper 225-150 CONC FL-FL	21/10/2010
78757	Superlink	Taper 225-200 CONC FL-FL	21/10/2010
78759	Superlink	Taper 250-100 CONC FL-FL	21/10/2010
78761	Superlink	Taper 250-150 CONC FL-FL	21/10/2010
78763	Superlink	Taper 250-200 CONC FL-FL	21/10/2010
78764	Superlink	Taper 250-225 CONC FL-FL	21/10/2010
78766	Superlink	Taper 300-100 CONC FL-FL	21/10/2010
78768	Superlink	Taper 300-150 CONC FL-FL	21/10/2010
78770	Superlink	Taper 300-200 CONC FL-FL	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
78772	Superlink	Taper 300-225 CONC FL-FL	21/10/2010
78774	Superlink	Taper 300-250 CONC FL-FL	21/10/2010
78776	Superlink	Taper 375-100 CONC FL-FL	21/10/2010
78778	Superlink	Taper 375-200 CONC FL-FL	21/10/2010
78780	Superlink	Taper 375-225 CONC FL-FL	21/10/2010
78782	Superlink	Taper 375-250 CONC FL-FL	21/10/2010
78784	Superlink	Taper 375-300 CONC FL-FL	21/10/2010
78306	Superlink	Tee 100-100 FL-FL-FL	21/10/2010
78319	Superlink	Tee 150-100 FL-FL-FL	21/10/2010
78949	Superlink	Tee 150-150 FL-FL-FL	21/10/2010
78999	Superlink	Tee 200-100 FL-FL-FL	21/10/2010
79009	Superlink	Tee 200-150 FL-FL-FL	21/10/2010
79019	Superlink	Tee 200-200 FL-FL-FL	21/10/2010
79038	Superlink	Tee 225-100 FL-FL-FL	21/10/2010
78406	Superlink	Tee 225-150 FL-FL-FL	21/10/2010
78696	Superlink	Tee 225-200 FL-FL-FL	21/10/2010
78422	Superlink	Tee 225-225 FL-FL-FL	21/10/2010
78699	Superlink	Tee 250-100 FL-FL-FL	21/10/2010
78447	Superlink	Tee 250-150 FL-FL-FL	21/10/2010
78702	Superlink	Tee 250-200 FL-FL-FL	21/10/2010
78704	Superlink	Tee 250-225 FL-FL-FL	21/10/2010
79124	Superlink	Tee 250-250 FL-FL-FL	21/10/2010
78707	Superlink	Tee 300-100 FL-FL-FL	21/10/2010
78708	Superlink	Tee 300-150 FL-FL-FL	21/10/2010
78710	Superlink	Tee 300-200 FL-FL-FL	21/10/2010
78712	Superlink	Tee 300-225 FL-FL-FL	21/10/2010
78714	Superlink	Tee 300-250 FL-FL-FL	21/10/2010



# Schedule

Model ID	Product Description		BSI Review Date
79199	Superlink	Tee 300-300 FL-FL-FL	21/10/2010
78717	Superlink	Tee 375-100 FL-FL-FL	21/10/2010
78719	Superlink	Tee 375-150 FL-FL-FL	21/10/2010
78721	Superlink	Tee 375-200 FL-FL-FL	21/10/2010
78723	Superlink	Tee 375-225 FL-FL-FL	21/10/2010
78725	Superlink	Tee 375-250 FL-FL-FL	21/10/2010
78727	Superlink	Tee 375-300 FL-FL-FL	21/10/2010
78729	Superlink	Tee 375-375 FL-FL-FL	21/10/2010
78651	Superlink	Tee 100-80 SP-SP-FL	21/10/2010
78911	Superlink	Tee 100-100 SP-SP-FL	21/10/2010
	Superlink	Tee 150-80 SP-SP-FL	21/10/2010
78939	Superlink	Tee 150-100 SP-SP-FL	21/10/2010
	Superlink	Tee 150-150 SP-SP-FL	21/10/2010
	Superlink	Tee 200-80 SP-SP-FL	21/10/2010
78998	Superlink	Tee 200-100 SP-SP-FL	21/10/2010
79000	Superlink	Tee 200-150 SP-SP-FL	21/10/2010
79018	Superlink	Tee 200-200 SP-SP-FL	21/10/2010
	Superlink	Tee 225-80 SP-SP-FL	21/10/2010
78653	Superlink	Tee 225-100 SP-SP-FL	21/10/2010
78655	Superlink	Tee 225-150 SP-SP-FL	21/10/2010
78657	Superlink	Tee 225-200 SP-SP-FL	21/10/2010
78659	Superlink	Tee 225-225 SP-SP-FL	21/10/2010
	Superlink	Tee 250-80 SP-SP-FL	21/10/2010
78660	Superlink	Tee 250-100 SP-SP-FL	21/10/2010
78661	Superlink	Tee 250-150 SP-SP-FL	21/10/2010
78662	Superlink	Tee 250-200 SP-SP-FL	21/10/2010
78664	Superlink	Tee 250-225 SP-SP-FL	21/10/2010

# Schedule

Model ID	Product Description		BSI Review Date
78665	Superlink	Tee 250-250 SP-SP-FL	21/10/2010
	Superlink	Tee 300-80 SP-SP-FL	21/10/2010
78666	Superlink	Tee 300-100 SP-SP-FL	21/10/2010
78668	Superlink	Tee 300-150 SP-SP-FL	21/10/2010
78670	Superlink	Tee 300-200 SP-SP-FL	21/10/2010
78672	Superlink	Tee 300-225 SP-SP-FL	21/10/2010
78674	Superlink	Tee 300-250 SP-SP-FL	21/10/2010
78676	Superlink	Tee 300-300 SP-SP-FL	21/10/2010
78678	Superlink	Tee 375-100 SP-SP-FL	21/10/2010
78680	Superlink	Tee 375-150 SP-SP-FL	21/10/2010
78682	Superlink	Tee 375-200 SP-SP-FL	21/10/2010
78684	Superlink	Tee 375-225 SP-SP-FL	21/10/2010
78686	Superlink	Tee 375-250 SP-SP-FL	21/10/2010
78688	Superlink	Tee 375-300 SP-SP-FL	21/10/2010
78690	Superlink	Tee 375-375 SP-SP-FL	21/10/2010